



Follow-up Service Inspection Report E1219761240319082952

INSPECTION DETAILS			
Date:	2024-03-19	File Number.:	E121976
Responsible Office:	Northbrook	Volume:	1
Inspection Center:	335	CCN:	PTKQ
Product Type:	Motors and Generators, Rebuilt for Use In Hazardous Locations	UL Rep Name:	Stuart Thomson
Deliverable Type:	Listed	UL Rep ID:	21167
Party Site Number:	604202	Subscriber Factory No.:	399460-001
Manufacturer Name:	Karsten Moholt A/S	Factory Rep Name:	Ms. Eva Kristin Tvedt
Manufacturer Address:	Varemottak Storebotn 70 Kleppesto	Factory Rep Phone:	+47-99631743
		Factory Rep Email:	eva.kristin.tvedt@karsten-moholt.no
Applicant:	Karsten Moholt A/S (604202) Varemottak, Storebotn 70 Kleppesto 5309 NO		
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	No	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental Conditions Required?	No

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
S0082639	Motors and Generators, Rebuilt for Use In Hazardous Locations	1	No

UL-OWNED EQUIPMENT CALIBRATION
No UL Owned IMTE used during inspection.

COMMENTS	
Additional Comments	The above motor is currently under investigation before being reworked. This will be a customer decision
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.